


# L B M

<三価クロメート>



呼称	Rc(PT)	E	I	H
LBM-1/8	1/8	12	18	14
LBM-1/4	1/4	15	24	19
LBM-3/8	3/8	17	27	24
LBM-1/2	1/2	22	34	27
LBM-3/4	3/4	27	40	32
LBM-1"	1"	32	43	41