


LCM

<三価クロメート>



呼称	Rc(PT)	R(PT)	E	l	d	H
LCM-1/8	1/8	1/8	12	21	4	14
LCM-1/4	1/4	1/4	15	27	7	19
LCM-3/8	3/8	3/8	17	32	9	24
LCM-1/2	1/2	1/2	22	38	12	27
LCM-3/4	3/4	3/4	27	44	16	32
LCM-1"	1"	1"	32	48	20	41